




# CN (No coin Mech) 60lb Express WCAD60KCB-CNSZ Diagram



P/N 9506-402-001PR  
WCAD60KCB-CNSZ 60LB EXPRESS W/NO COIN ACCEPTOR  
WITH START AND STOP BUTTONS

COIN PULSE WIDTH MUST BE  
50mSec TO 200mSec

WIRING DIAGRAM 208-240V-3/1PH-60HZ