


WIRING DIAGRAM 400V, 3PH, 50HZ

P/N 9507-035-001A
 60 LB OPL EXPRESS, VF DRIVE
 ELECTRIC HEAT
 WN950EA-68_0_X-____-__X

400V-3PH-50HZ

WATER VALVES	
H2	- HOT SOAP
H1	- HOT TUB
H3	- HOT TUB
C2	- COLD SOFTENER
C1	- COLD TUB
C3	- COLD TUB



SCHEMATIC

400V-3PH-50HZ

P/N 9508-035-001A
 60 LB OPL EXPRESS, VF DRIVE,
 HEATED